

Fig.1A




Fig.1B




Fig.1C




Fig.2A




Fig.2B




Fig.2C




Fig.3

RELIABILITY EXAMINATION (50°C, 300mW)

HEAT TREATMENT: 820°C, N=10




Fig.4




Fig.5




Fig.6




Fig.7

